

## DIR-878 Firmware Release Notes

**Firmware: FW104**

**Hardware: Rev. Ax**

**Release Date: 2018/3/9**

### **Note:**

1. The firmware v1.04 is the transitional version for upgrading to v1.10 or later version.
2. Below is the procedure for firmware upgrade:
  - Connect to the router via LAN port or WIRELESS interface.
  - Log in to the D-Link management page (<http://192.168.0.1> or [http://dlinkrouter.local./](http://dlinkrouter.local/))
  - Go to the firmware upgrade page, upload the firmware v1.04 and wait for the device to reboot.
  - Log in to the D-Link management page again.
  - Go to the firmware upgrade page and check the button of online firmware check and download the firmware v1.10 or later version.
  - Upload the firmware v1.10 or later version.
  - Wait for the device to reboot and don't power off the router during the firmware upgrade.
  - The router is fully upgraded.