

DIR-878 Firmware Release Notes

Firmware: FW110

Hardware: Rev. Ax

Release Date: 2018/3/09

Note:

1. The firmware version is advanced to v1.10
2. The firmware v1.10 must be upgraded from the transitional version of firmware v1.04 (transitional version).

Problems Resolved:

1. Update wpa2 security patch
2. Support EU VLAN @ EU country code
3. Support VLAN profile @ SG country code
4. Upgrade dnsmasq to 2.78

Enhancements

1. Support D-Link Wi-Fi APP
(QRS mobile won't be supported from firmware version v1.10 or later version)
2. Support image with encryption