



DIR-868L Firmware Release Notes

Firmware: FWv1.21SHC

Hardware: Rev.A1

Release Date: 2017/12/19

Note:

1. The firmware version is advanced to v1.21SHC
2. The firmware v1.21SHC must be upgraded from the transitional version of firmware v1.10SHC.
3. The reported exploit below are found by "Tony Loi of Fortinet's FortiGuard Labs <http://www.fortiguards.com/>"
4. Enhance WPA security vulnerabilities

Problems Resolved:

1. Fixed the security issues reported by Tony Loi on October 24th, 2017.
 - Buffer overflow issue in authentication request (cgibin)
2. Fix Wi-Fi Krack vulnerability